



Docket No.: 206379US40PCT

OBLON
SPIVAK
MCCLELIAND
MATER
&
NEUSTADT
P.C.

COMMISSIONER FOR PATENTS ALEXANDRIA, VIRGINIA 22313

ATTORNEYS AT LAW

RE: Inventor: Masato TAKAHASHI

Patent No.: 6,999,162 Issued: February 14, 2006 Group Art Unit: 2851 Examiner: KIM, PETER B

For: STAGE DEVICE, EXPOSURE SYSTEM, METHOD

OF DEVICE MANUFACTURE, AND DEVICE

Certificate
JUN 1 4 2006

of Correction

SIR:

Attached hereto for filing are the following papers:

## REQUEST FOR CERTIFICATE OF CORRECTION CERTIFICATE OF CORRECTION FORM PTO 1050

Our check in the amount of \$0.00 is attached covering any required fees. In the event any variance exists between the amount enclosed and the Patent Office charges for filing the above-noted documents, including any fees required under 37 C.F.R 1.136 for any necessary Extension of Time to make the filing of the attached documents timely, please charge or credit the difference to our Deposit Account No. 15-0030. A duplicate copy of this sheet is enclosed.

Respectfully Submitted,

OBLON, SPIVAK, McCLELLAND, MAIER & NEUSTADT, P.C.

Richard D. Kelly

Registration No. 27,757 Raymond F. Cardillo, Jr. Registration No. 40,440

Customer Number

22850 Tel. (703) 413-3000 Fax. (703) 413-2220

(OSMMN 03/06)

DOCKET NO.: 206379US40PCT/smc



IN RE APPLICATION OF: Masato TAKAHASHI

PATENT NO.: 6,999,162

GROUP: 2851

ISSUED: February 14, 2006

EXAMINER: KIM, PETER B

FOR: STAGE DEVICE, EXPOSURE SYSTEM, METHOD OF DEVICE

MANUFACTURE, AND DEVICE

## **REQUEST FOR CERTIFICATE OF CORRECTION**

DIRECTOR OF THE UNITED STATES PATENT AND TRADEMARK OFFICE ALEXANDRIA, VA 22313-1450

SIR:

The following is a Request for Certificate of Correction in Serial Number 09/830,684, now U.S. Patent Number 6,999,162.

In accordance with the provisions of Rule 322 of the Rules of Practice, which implement 35 USC 254, the U.S. Patent and Trademark Office is respectfully requested to issue a Certificate of Correction in the above-identified patent.

In light of the fact that the errors were the fault of the U.S. Patent and Trademark Office, no fees are required. The requested corrections are listed on FORM P.T.O. 1050.

Respectfully Submitted,

OBLON, SPIVAK, McCLELLAND,

MAIER & NEUSTADT, P.C.

Richard D. Kelly

Registration No. 27,757 Raymond F. Cardillo, Jr.

Registration No. 40.440

Customer Number

22850

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 03/06)

~~ ^ \\ . ·

UNITED STATES PATENT AND TRADEMARK OFFICE

## CERTIFICATE OF CORRECTION

PATENT NO.:

6,999,162

DATED:

Feb. 14, 2006

INVENTOR(S):

Takahashi

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page, Item (75), the inventor's residence is incorrect. Item (75) should read:

-- (75) Inventor: Masato Takahashi, Kumagaya (JP) --

Mailing address of sender:

Patent No.

6,999,162

Customer Number

22850

No. of add'l copies @ .30 per page

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 03/06)



UNITED STATES PATENT AND TRADEMARK OFFICE

## CERTIFICATE OF CORRECTION

PATENT NO.:

6,999,162

DATED:

Feb. 14, 2006

INVENTOR(S):

Takahashi

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page, Item (75), the inventor's residence is incorrect. Item (75) should read:

-- (75) Inventor: Masato Takahashi, Kumagaya (JP) --

Mailing address of sender:

Patent No.

6,999,162

Customer Number

22850

No. of add'l copies @ .30 per page

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 03/06)

